

## TECHNICAL ADVISES CABLE RAMPS

(Translation)

### Cable Ramp

Upper part black or yellow with insert

Dimensions: (LxHxW): 800 x 600 x 80 mm

Cable Ramp: Ref. 25931N11, 25931N11GELB

The above described products are exclusively applicable for use on roads in traffic calmed zones: traffic calmed zones are considered as such if there is only maximum walking speed allowed, if the traffic volume is very low and if the traffic shows only a low percentage of heavy trucks!

Please consider that the below described treatment or application of the cable ramp does not correspond to the intended purpose and will significantly reduce the lifetime of the product or even may lead to its destruction:

- Frequent overrunning by heavy trucks
- High percentage of heavy truck traffic
- Frequent overrunning with average speed higher than walking speed (>7 km/h)
- Over running rolling by construction vehicles/machines or other special vehicles / machines
- Overrunning with snow ploughs

### Additionally

- Improper installation
- Freeze
- De-icing salt
- Grit
- Bad or bumpy ground
- Installation on pavement

will re-enforce the negative effects.

In case of non-compliance with the technical advises, horizont-klemmfix cannot be liable for a reduced life-time of the product.

Dieses Schreiben wurde EDV-gesteuert übermittelt und ist ohne Unterschrift gültig

Geschäftsführer	Banken	BLZ	Konto-Nr.	BIC	IBAN	USt-ID-Nr.	Gläubiger-ID-Nr.
Dipl.-Ing. Dirk Trompeter	Commerzbank AG	520 400 21	5300076	COBA DE 3300	DE94 5204 0021 0300 0076 00	DE 113074919	DE29ZZ00000351848
Dipl.-Ing. Robert Müller	Sparkasse WLFab	523 900 05	1222	HELA DE 3300	DE28 5239 0005 0000 0012 22		
Dipl.-Kfm. Steffen Müller	Kasseler Bank eG	520 900 00	50131009	GENO DE 51K51	DE97 5209 0000 0050 1310 09	Amtsgericht Korbach	
Dipl.-Öt. Dieter Heiler	Volksbank Bawling	692 011 20	2694006	GENO DE 51V6K	DE17 6920 1120 0002 8340 06	1 V11 B 100	
Dipl.-BW Gerd Christiani							

## Safety Instructions

Overrunning the cable ramp with speeds higher than walking speed (> 7 km/h) may lead to damages at the vehicle, especially if the vehicle has a low chassis clearance (e.g. sport cars or cars with a lowered chassis)

Overrunning of the cable ramp with single track vehicles (e.g. bicycles or motorbikes), especially in bad weather conditions may lead to falls..

horizont klemmfix therefore highly recommends to set up warning signs, indicating that there is an obstacle on the road, advising to drive carefully and not faster than 7 km/h.

Dieses Schreiben wurde EDV-gesteuert übermittelt und ist ohne Unterschrift gültig

Geschäftsführer	Banken	BLZ	Konto-Nr.	BIC	IBAN	USt-ID-Nr.	Gläubiger-ID-Nr.
Dipl.-Ing. Dirk Trompeter	Commerzbank AG	520 400 21	5300076	COBA DE 3300	DE94 5204 0021 0300 0076 00	DE 113074919	DE29ZZ00000351848
Dipl.-Ing. Robert Müller	Sparkasse WLFab	523 900 05	1222	HELA DE 3300	DE28 5239 0005 0000 0012 22		
Dipl.-Kfm. Steffen Müller	Kasseler Bank eG	520 900 00	50131009	GENO DE 51K51	DE97 5209 0000 0050 1310 09	Amtsgericht Korbach	
Dipl.-Öt. Dieter Heiler	Volksbank Bawling	692 011 20	2694006	GENO DE 51V6K	DE17 6920 1120 0002 8340 06	1 V11 B 100	
Dipl.-BW Gerd Christiani							